



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D4030-041
Job Sheet 183121



Part No: D4030-041

Job Qty: 1 ea

Part Name: Long Basket Assembly (350)



Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 9/12/18

Job Tracking No:

Due Date: 9/21/18

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: DWG REV D SHEETS 1,3,4 IPP Rev:A new issue DD 10.03.23 verified by:EC IPP Rev:B as per dwg revB DD 10.04.20 verified by:EC IPP Rev:C as per dwg revC DD 10.08.18 verified by:EC IPP Rev D 12.03.27 per NCR12-1239 EC verified by:JLM

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea	9/21/18	9/21/18	0.00	0.00	Start Up Stores/Pkg-1		ML 18-10-03
100	Packaging	1 pcs	9/21/18	9/21/18	0.00	0.00	Packaging1-4		ML 18-10-03
110	HandFinish	1 pcs	9/21/18	9/21/18	0.00	1.03	HandFinish4		ML 18-10-03
120	QC	1 pcs	9/21/18	9/21/18	0.00	0.00	QC5		ML 18-10-03
130	Packaging	1 pcs	9/21/18	9/21/18	0.00	0.00	Packaging3-2	OCT 04 2018	ML 18-10-03
140	QC21-SA	1 Ea	9/21/18	9/21/18	0.00	0.00	QC21		ML 18-10-03

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
AN3-14A	Bolt	4 Ea (4 ea)	90-Start up Operation	5068652
AN3-16A	Bolt	2 Ea (2 ea)	90-Start up Operation	5089276
AN310-4	Nut	3 Ea (3 ea)	90-Start up Operation	5082904-1
AN310C4	Nut	2 Ea (2 ea)	90-Start up Operation	5065269
AN4-12	Bolt	3 Ea (3 ea)	90-Start up Operation	5074206-1
AN5-17A	Bolt	4 Ea (4 ea)	90-Start up Operation	5068646
D2530	Handle Weldment	1 Ea (1 ea)	90-Start up Operation	5109650
D2535	Spring	2 Ea (2 ea)	90-Start up Operation	5097106
D2537	Bushing	2 Ea (2 ea)	90-Start up Operation	511545
D3917-3	Washer	6 Ea (6 ea)	90-Start up Operation	5115446(x2)
D3953-17	Gas Spring Spacer	2 Ea (2 ea)	90-Start up Operation	5072726
D3953-19	Gas Spring Bracket	1 Ea (1 ea)	90-Start up Operation	5068384
D3953-21	Gas Spring Bracket	1 Ea (1 ea)	90-Start up Operation	5112717
D3953-3	Gas Spring Stud, Lid	2 Ea (2 ea)	90-Start up Operation	5112581
D3953-7	Spring Spacer	2 Ea (2 ea)	90-Start up Operation	5097232
D3953-9	Gas Spring Washer	2 Ea (2 ea)	90-Start up Operation	5115399
D3969-3	Spring (Basket Lid)	1 Ea (1 ea)	90-Start up Operation	5089207
MS21042L3	Nut	6 Ea (6 ea)	90-Start up Operation	5078253
MS21042L5	Nut	4 Ea (4 ea)	90-Start up Operation	5083541
MS24665-151	Cotter Pin	3 Ea (3 ea)	90-Start up Operation	5053951-1
MS24665-300	Cotter Pin	2 Ea (2 ea)	90-Start up Operation	5044188-1
NAS1149C0432R	Washer	2 Ea (2 ea)	90-Start up Operation	5050052-1
NAS1149F0332P	Washer	8 Ea (8 ea)	90-Start up Operation	5103666-1

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER :					

NAS1149F0432P	Washer	6 Ea (6 ea)	90-Start up Operation
NAS1149F0563P	Washer	4 Ea (4 ea)	90-Start up Operation
D3913-041	Long Basket Base Assembly, 350	1 Ea (1 ea)	110-HandFinish
D3914-041	Long Basket Lid Assembly (350)	1 Ea (1 ea)	110-HandFinish

5083558-1
5067901-2
511446
511281

Job Allocations

005769

Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	AN3-14A	4	101	0
	AN3-16A	2	118	0
	AN310-4	3	115	0
	AN310C4	2	143	0
	AN4-12	3	73	0
	AN5-17A	4	102	0
	D2530	1	18	0
	D2535	2	54	0
	D2537	2	12	0
	D3917-3	6	21	0
	D3953-17	2	21	0
	D3953-19	1	26	0
	D3953-21	1	10	0
	D3953-3	2	4	0
	D3953-7	2	20	0
	D3953-9	2	7	0
	D3969-3	1	18	0
	MS21042L3	6	3,308	0
	MS21042L5	4	892	0
	MS24665-151	3	252	0
	MS24665-300	2	128	0
	NAS1149C0432R	2	2,781	0
	NAS1149F0332P	8	1,625	0
	NAS1149F0432P	6	1,559	0
	NAS1149F0563P	4	966	0
110-HandFinish	D3913-041	1	2	0
	D3914-041	1	2	0

Part Specifications

Specifications could not be found.

DART
AEROSPACE

Container No: S115723



Part: D4030-041

Job No: 183121

Serial No/Batch: S115723

Revision:

Inspector:

Exp Date:

Instructions: Various STC's

1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 813 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Date: 10/03/18

Plex 9/12/18 2:42 PM Dart.lajeunesse.marie

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : _____					